



Weld only on this side of washer,
Weld must penetrate both tubes
and washer.

R.13
.75 X .049 4130 tube



.875 X .058 4130 steel tube

2" X .75" X .125 washer



SCALE 1.000

	Super2		
	Main Gear Spring Support tube		
Aug15st, 2012			